

FASTCAM-Series DRIVER CD-ROM Rev. 2.40.40			Release Note
			2007/01/30
CD-ROM Revision FASTCAM-Series DRIVER CD-ROM Rev.2.40.40 (Domestic/Overseas common shipment version)			
PFV Revision PFV Ver.2440 SDK Ver.2980			
The contents of a folder in CD-ROM			
PFV setup	PFVSETUP		
Driver	Device driver FASTCAM-Ultima1024 FASTCAM-Ultima SE FASTCAM-PCI FASTCAM-PCI R2 FASTCAM-X1280PCI FATSCAM-ultima APX FATSCAM-ultima 512 FATSCAM-512PCI FASTCAM-APX RS FASTCAM-1024PCI		
SDK	FASTCAM series correspondence SDK ,Sample code ,SDK document		
Doc	PDF file inclusion of each camera manual ,Release Note		
DirectX	Microsoft DirectX Run time		

Functional addition		Bug fixed	Others
No.	Contents		Hardware Update
FASTCAM-APX			
1	With the Image-intensified FASTCAM-APX (FASTCAM-APX I.I.) the I.I. (image intensifier) gain setting unit has been changed from one digit to two digits below the decimal point.		Needed
2	Fcam1394.dll changed (Ver.2.014).		
3	FcamOpt.dll changed (Ver.1.025).		
4	FcamEth.dll changed (Ver.1.026).		
FASTCAM-1024PCI			
5	With the FASTCAM-1024PCI, the defect has been corrected in which the shutter speed setting erroneously gets open when the system is switched from the memory mode to live mode while the system is operating in the external sync mode.		
6	FcamPPCI.dll changed (Ver.1.009).		
FASTCAM-512PCI			
7	With the FASTCAM-512PCI, the defect has been corrected in which the shutter speed setting erroneously gets open when the system is switched from the memory mode to live mode while the system is operating in the external sync mode.		
8	FcamNPCI.dll changed (Ver.1.014).		
PFV-SDK			
9	The defect has been corrected in which there was occasional offset of one (1) frame in the “Hour” time display in the T-axis indication of graphic display.		

End of documents